



**N. B.:** The above marked areas (four locations) beneath the Tower Pulley Structure are to be checked/inspected for cracks by carrying out Non-Destructive Testing and to be rectified by welding, in case of any cracks.