



मुरगांव पत्तन प्राधिकरण

MORMUGAO PORT AUTHORITY









TM/2/48/2023/01714

Date: 03.11.2023

Trade Circular No. 13/2023

Sub: Spillage of cargo from trucks/tippers.

Instances have been reported of the trucks being over-heaped (higher than the coaming of truck hatch) with cargo and it may results in spillage of cargo on the roads whilst it is being transported. This has led to complaints being from different agencies/organizations/statutory authorities.

As a responsible authority the Port has taken cognizance of the above and accordingly it is decided that no trucks shall be permitted to GATE OUT from MPA if it is over- heaped and not covered and secured with proper tarpaulins. Trucks shall be loaded up to the body level only. Any truck found not in compliance with the above will not be permitted to gate out.

Further, CISF is hereby directed not to permit GATE OUT of any trucks/tippers violating above direction/instructions, and also to maintain and report such non-compliance on a daily basis. Repeated actions of violations shall be penalized and blacklisted.

This issues with the approval of the competent authority.

(Deelip Halarnkar) MANAGER (OPN.)

To,

- 1. The President, Mormugao Stevedores Association
- 2. M/s. Adani
- 3. M/s. JSW
- 4. All Stake Holders

Copy for kind information to:

- 1. Chairperson
- 2. Dy. Chairperson
- 3. TM/SDTM
- 4. Dy. Conservator
- 5. FA&CAO
- 6. All officers of Traffic Dept.
- 7. Hindi Section for Hindi version
- 8. MPA Website