

MORMUGAO PORT TRUST, GOA
Serving the Nation since 1885
(Ministry of Shipping, Government of India)



TM/ 593 /2018/295 Date: 02/05/2018

TRADE CIRCULAR NO. 5/2018

During the site inspection it has been observed that two approaches to berth No. 9 are in dilapidated conditions and hence unsafe for traffic movement. The Civil Engineering Department has therefore advised to barricade the two approaches and only make available the middle approach bridge for operational purpose.

It is therefore, requested to advise all your staff and workers to kindly use only middle bridge for safe passage of traffic movement to and from the berth No. 9.

This circular is issued for the information of the Members of the Trade and with a request to inform all the stake holders for compliance.

TRAFFIC MANAGER

To, President, Stevedores Association President, Ship Agents' Association

Copy for kind information to: Chairman's Office/Dy. Chairman's Office/ / CE/ Manager (Ops.)/Safety Officer, CME Department

MPT website Hindi Section